

Fall Winter 25/26 | Stock Service Tejido Industrial | Essentials | Kori



INDUSTRIAL FINISHING

- After knitted process stabilize the panel by steaming or immersing in hot water, cooling them off in water, and softening at 30 degrees using the products of your choice on a delicate-fabrics wash cycle; then it should be given another spin. You may need to accommodate the fabric after spinning; this should be done with a manual steam iron before starting the drying process.

COLORS AVAILABLE

Refer to Stock Service Color Card

>

CARE INSTRUCTION			COLOR FASTNESS (AVERAGE VALUES)				
	Any solvent except rrachiorethylene	Iow Do not bleach	Light Medium Dark	Dry rubbing 4 3	Wet rubbing 4 3 2/3	Wash fastness 4 4 3	
TECHNICAL INFORMATION		KETTLE SIZE (Kg.)	SUGGESTED GAUGE		CERTIFICATION		
Dyeing method Knot type Pilling	Hanks Splicer 3.5	30 40 80 200	14gg		CONFIDENCE IN TEXTILES STANDARD 100 16.HPE.92779 HOHENSTEIN HTTI Tested for harmful substances. www.ocket.acconstanted100		

NOTES:

- Might occur bleeding in design with white stripes and intense colors.
- Consult our sales team about dyeing process that decrease bleeding risk on intense colors.
- Minimum for dark colors subject to revision.