


Fall Winter 25/26 | Stock Service Tejido Industrial | Essentials | Nuna Brushed

## NUNA BRUSHED






## INDUSTRIAL FINISHING

- We recommend washing at 35° in gentle cycle during 3 minutes using a softener that does not exceed 4% of the weight of the material considering the finishing expected. Centrifuge for 2 minutes. Dry. Use manual iron. If a more pronounced pile is required, washing time or washing cycle revolutions should be increased, but the bath temperature must be reduced to avoid the felting effect.

COLORS AVAILABLE

Refer to Stock Service Color Card

>



NOTES:

- Might occur bleeding in design with white stripes and intense colors.
- · Consult our sales team about dyeing process that decrease bleeding risk on intense colors.
- Minimum for dark colors subject to revision.