

17



INDUSTRIAL FINISHING

We recommend to seteam first, then dry cleam with any solvent depending of the result you want to obtain. After this steam the garment without pressuring the knitted panel.



Bleeding might occur in designs with white stripes and intense colours. Please consult us for further details.



BRAND LABEL



TRACEABILITY OF YARN BACK TO FARMING



- Hangtags are available free of cost, 3 pieces per 1kg of yarn.
- Oeko-Tex standard class II, depending on colour. Some dark colours do not qualify for Oeko Tex.