

ANDEAN HIGHLAND WOOL

COMPOSITION
100% Andean Highland Wool

NM
2/3.5

Color Card



PRESENTATION

Cone
1 kg

INDUSTRIAL FINISHING


- We recommend washing at 20° in gentle cycle during 3 minutes using a softener that does not exceed 4% of the weight of the material considering the finishing expected. Centrifuge for 2 minutes. Dry. Use manual iron. Should felting occur, exposure time to the washing process should be reduced.

COLORS AVAILABLE



Refer to Stock Service Color Card

CARE INSTRUCTION



COLOR FASTNESS (AVERAGE VALUES)

	Dry rubbing	Wet rubbing	Wash fastness
Light	4	4	4
Medium	4	3	4
Dark	3	2/3	3

TECHNICAL INFORMATION

Dyeing method **Hanks/Tops**
Knot type **Splicer**
Pilling **3**

KETTLE SIZE (Kg.)

Hanks	Tops
30	50
40	100
80	200
200	

SUGGESTED GAUGE

3gg

CERTIFICATION



NOTES:

- For minimum production quantities and custom made colors please contact our sales representative.