

Fall Winter 25/26 | Stock Service Tejido Industrial | Essentials Vibes | Pujpu Light

PUJPU LIGHT





INDUSTRIAL FINISHING We recommend washing at 35° in gentle cycle during 3 minutes using a softener that does not exceed 4% of the weight of the material considering the finishing expected. COLORS AVAILABLE > Refer to Stock Service Color Card Centrifuge for 2 minutes. Dry. Use manual iron. If the fabric turns out excessively felted, the washing time or temperture should be reduced. COLOR FASTNESS (AVERAGE VALUES) CARE INSTRUCTION Dry rubbing Wet rubbing Wash fastness ٠ 3 4 Light 4 Any solvent except tetrachiorethylene Iron low Do not bleach Dry flat Medium 4 3 3/4 Hand wash Dark 3 2/3 3 TECHNICAL KETTLE SIZE (Kg.) SUGGESTED GAUGE CERTIFICATION INFORMATION **OEKO-TEX**® Dyeing method Tops 50 3gg 100 200 CONFIDENCE IN TEXTILES STANDARD 100 16.HPE.92779 HOHENSTEIN HTTI Tested for harmful substances. www.eeko-tex.com/standard100 Knot type Knot Pilling 3

NOTES:

- Might occur bleeding in design with white stripes and intense colors.
- Consult our sales team about dyeing process that decrease bleeding risk on intense colors.
- Minimum for dark colors subject to revision.